


Definition and measurement

zondag 4 december 2016 11:11

Definition

- Elasticity
 - o Reversible
- Plasticity
 - o Irreversible

Metals



- After yield point : metals work harden
- After tensile strength : necking (= deformation)

Polymers




Figure 6.2 Stress-strain curve for a polymer.

- Dependent of T in comparison to T_g
- $T \ll T_g$
 - o Polymers are brittle
- $T < T_g$
 - o Plasticity becomes possible
- $T = T_g$
 - o Cold drawing : large plastic extension , the molecules are pulled into alignment with the direction of straining , followed by hardening and fracture

- $T \gg T_g$
 - o Thermoplastics become viscous and can be moulded, become rubbery and decompose

Ceramics




Figure 6.3 Stress-strain curve for a ceramic.

- Brittle at room temperature
- They have a yield strength, but they are so high that they are never reached in tension
 - o They fracture first
- They measure it with the term compressive crushing strength
 - o We call it elastic limit, because it is not the true yield
 - o σ_{el}

Plastic strain

- ϵ_{el}
 - o Permanent strain resulting from plasticity
 - o Total strain ($= \epsilon_{tot}$) minus the recoverable, elastic part

$$\epsilon_{pl} = \epsilon_{tot} - \frac{\sigma}{E}$$

Ductility

- A measure of how much plastic strain a material can tolerate
- ϵ_f = elongation = tensile strain at break


Plastic work

- Deforming a material permanently by yield or crushing

$$W_{pl} = \int_0^{\epsilon_f} \sigma d\epsilon_{pl}$$

- o Area under stress-strain curve





True versus nominal

$$\sigma_t = \frac{F}{A}$$


$$V = A_0 L_0 = A L$$

$$\sigma_n = \frac{F}{A_0} = \frac{F}{A} \frac{L_0}{L}$$

$$\epsilon_n = \frac{\delta L}{L_0} = \frac{L - L_0}{L_0} = \frac{L}{L_0} - 1$$



$$\sigma_t = \sigma_n(1 + \epsilon_n)$$

$$\Rightarrow \epsilon_t = \int_{L_0}^L \frac{dL}{L} = \ln\left(\frac{L}{L_0}\right) = \ln(1 + \epsilon_n)$$



Hardness test

$$H = \frac{F}{A}$$




- Vickers

$$H_v \approx \frac{\sigma_y}{3}$$


Charts for yield strength

zondag 4 december 2016 12:08

Strength-density chart



Modulus-strength chart




Origins of strength and ductility

zondag 4 december 2016 12:11

Perfection : the ideal strength

- Bonds between atoms have a breaking point
- When you pull them apart from distance a_0 to a^* , they will go to maximum stress, and then go apart



- Force needed to break a bond is roughly (broken when stretched to more than 10% of original length)

$$F \approx \frac{S a_0}{10}$$

- Ideal strength should be

$$\sigma_{\text{ideal}} = F_{\max}/a_0^2 = S/10a_0 = E/10$$

$$\frac{\sigma_{\text{ideal}}}{E} \approx \frac{1}{10}$$

Crystalline imperfection : defects in metals and ceramics




Figure 6.10 Defects in crystals. (a) Vacancies—missing atoms. (b) Foreign (solute) atom on interstitial and substitutional sites. (c) A dislocation—an extra half-plane of atoms. (d) Grain boundaries.

- a) Vacancies
 - Point defects
 - An atom is missing
 - They do not influence strength, the others do
- b) Solutions :
 - Substitutional solid solution
 - Dissolved atoms replace those of the host
 - Interstitial solid solution
 - Dissolved atoms squeeze into the spaces
 - Makes them stronger
- c) Dislocation
 - Upper part of the crystal has one more double-layer of atoms than the lower part
 - Makes metals soft and ductile
- d) Grain boundaries
 - Perfect , but differently oriented, crystals meet
 - They are all the same atoms

Dislocations and plastic flow

- How to make a dislocation





Figure 6.11 (a) Making a dislocation by cutting, slipping and rejoining bonds across a slip plane. (b) The atom configuration at an edge dislocation in a simple cubic crystal. The configurations in other crystal structures are more complex but the principle remains the same.

- Crystal is cut along an atomic plane
 - Top part is slid across the bottom by one full atom spacing
- Beweging door aanbrenging van schuifspanning τ



- Schroefdislocatie







Figure 6.13 A screw dislocation. The slip vector b is parallel to the dislocation line $S-S$.

- Dislocation motion causes extension, at constant volume



Why does a shear stress make a dislocation move?

- For yielding to take place the external stress must overcome the resistance f





Figure 6.15 The force on a dislocation. (a) Perspective view. (b) Plan view of slip plane.

- $$W = \tau L_1 L_2 b$$

- $$\tau b = f$$

Line tension


- $$T \approx \frac{1}{2} E b^2$$



Lattice resistance (= rooster weerstand)

- f_i
 - Intrinsic resistance of the crystal structure to plastic shear
- Metalen kunnen op verschillende manieren versterkt worden
 - $f = f_i + f_{ss} + f_{ppt} + f_{wh} + f_{gb}$
 - f_{ss} = solid solution hardening
 - f_{ppt} = precipitation hardening
 - f_{wh} = work hardening
 - f_{gb} = grain-size hardening

Plastic flow in polymers




Manipulating strength

zondag 4 december 2016 12:47

Strengthening metals


- The way to make crystalline materials stronger is to make it harder for dislocations to move
 - o Dislocations move in a pure crystal when $\tau b > f_i$



- In perfect lattice, the only resistance is intrinsic strength
- Atom-size obstacles to motion
- Presents larger obstacles
- Slip plane becomes stepped and threaded with forest dislocations

- Number of obstacles touching unit length of dislocation line

$$N_L = \frac{1}{L}$$



- Each individual obstacle exerts a pinning force p on the dislocation line

$$f = \frac{p}{L}$$

- The shear stress τ needed to make the dislocation move


$$\Delta\tau = \frac{p}{b L}$$

- Pinning is an elastic effect
 - o When the dislocation moves, it produces plastic deformation
- The shear stress τ needed to force the dislocation through the field of obstacles

$$\tau = \alpha \frac{E b}{L}$$

- α is dimensionless, constant = sterkte van obstakel

Solution hardening





- Strengthening by deliberate additions of impurities, by alloying

$$c = \frac{b^2}{L^2}$$

- b = atoomgrootte
- L = afstand tussen opgeloste atomen

$$\tau_{ss} = \alpha E c^{\frac{1}{2}}$$


Dispersion and precipitate strengthening



$$\tau_{ppt} = \frac{2T}{bL} \approx \frac{Eb}{L}$$

$$f_{ppt} = 2 \frac{T}{L}$$

Work hardening



$$L = \mathbf{\rho}_d^{-1/2}$$

$$p = E \frac{b^2}{2}$$

$$\tau_{\text{wh}} \approx \frac{E b}{2} \sqrt{\rho_d}$$


Grain boundary hardening

$$\tau_{\text{gb}} = \frac{k_p}{\sqrt{D}}$$

- D = korrelgrootte
- k_p = Hall-Petch constante



Relationship between dislocation strength and yield strength

$$\tau_y = \tau_i + \tau_{ss} + \tau_{ppt} + \tau_{wh} + \tau_{gb}$$




- Shear stress
 - $\tau = \frac{F \sin \theta}{A / \cos \theta} = \sigma \sin \theta \cos \theta$
- Maximum shear stress
 - $\tau = \frac{\sigma}{2}$
- $\sigma_y \approx 3\tau_y$

Strength and ductility of alloys




Strengthening polymers

- Versteven door
 - Mengen van meerdere polymeren
 - Trekken



- Kruisverbindingen



- Verstevigende deeltjes of vezels